



FIRE RESISTANT TIMBER DOOR SCHEME

Certificate Number: IFCC 1503

This is a product certificate to certify that

Solidcor Limited

Whittington Way,
Chesterfield
S41 9AG
UK

Telephone no. 01246 264245

who fabricate the following timber fire doors:

Solidcor Fire & Smoke Door System R30 DOORSET

have satisfied the requirements of the SDP01 Fire resistant Timber Door scheme. This includes the testing of products to **EN1634-1 and EN1634-3**, the inspection of Factory Production Control and continuing surveillance audits and testing of samples of products taken from production. The product specification and field of application to achieve from **30 minutes** are detailed on page 2 of this certificate.



Initial certification: 25 June 2019
Revised: 02 March 2020
Valid to: 24 June 2024
Issue status: 2

Ian Woodhouse
Director of Certification



175

IFC Certification Ltd
20 Park Street, Princes Risborough, Buckinghamshire. England HP27 9AH
Tel: +44 (0)1844 275500 Fax: +(0)1844 274002 E-mail: info@ifccertification.com Web: www.ifccertification.com
Registered No: 4777898 England

The certificate and schedule are held in force by regular annual surveillance visits by IFC Certification and the reader or user should contact IFC Certification to validate its status. This certificate remains the property of IFC Certification and must be returned to them on demand.

F27 ©IFC Certification Ltd 2004

Certificate number: IFCC 1503

The production of fire resistant timber doorsets are manufactured in accordance with assessment/ test reports referenced within the following table:

Doorset Description	Fire Rating	Assessment/ Test Report
R30 Doorsets	FD30	PAR/19437/01
R30 Doorsets	Smoke	W18322-4 W18322-5

The scope of the certification is limited to the details and parameters contained within these reports and all aspects of the specification and limitations defined therein must be satisfied.

It is the certificate holder's responsibility to ensure that the latest version/ revision of the above assessment reports are maintained as part of the audited FPC system.

Failure to comply with all specifications will invalidate the certification and may jeopardise the fire performance.