





FIRE RESISTANT TIMBER FIRE DOORS

Certificate number: IFCC 1503

Certificate only valid if verified on website – www.ifccertification.com

Issued by IFC Certification Ltd part of the Kiwa UK Group

This is to certify that

Solidcor Ltd

Unit 5, Sheepbridge Lane Chesterfield S41 9RX Tel: 01246 264245

Who fabricate the following timber fire doors and or doorsets:

Solidcor Fire & Smoke Door System R30 & R60 DOORSETS

have satisfied the requirements of the SDP01 Fire resistant Timber Door scheme. This includes the testing of products to EN1634-1 and EN1634-3, the inspection of Factory Production Control and continuing surveillance audits and testing of samples of products taken from production. The product specification and field of application to achieve from 30 minutes to 60 minutes are detailed on page 2 of this certificate.

> Initial Certification: 25 June 2019 Reissued: 23 November 2023 Valid to: 24 June 2024 Issue number: 5

Ian Woodhouse Head of Technical - IFC Certification Kiwa Ltd

This certificate consists of 2 pages. Publication of this certificate is permitted.

IFC Certification Ltd

Ground Floor, Suite A, Building 2

Bear Brook Office Park

Walton Street

Aylesbury

Buckinghamshire

HP21 7GQ United Kinadom

T +44 (0)1844 276920

www.ifccertification.com









The production of fire-resistant timber doorsets are manufactured in accordance with assessment/ test reports referenced within the following table:

Doorset Description	Fire Rating	Assessment/Test Report
R30 Doorsets	E30	PAR/19437/01
R30 Doorsets with Fanlights	E30	CFR200626_1
R30 Doorsets with Sidelights and Fanlights	E30	WF520980/R
R30 Brampton	El30	EUI-20-B-000196B
R30/R60 Doorsets	Smoke	W18322-4 W18322-5
R30 with Fanlight	Smoke	W20174-1
R60 Doorsets	E60	PAR/22410/01

Signed on behalf of Kiwa Ltd

Jan Waadhayaa

Ian Woodhouse Head of Technical – IFC Certification Kiwa Ltd

The scope of the certification is limited to the details and parameters contained within these reports and all aspects of the specification and limitations defined therein must be satisfied

It is the certificate holder's responsibility to ensure that the latest version/ revision of the above assessment reports are maintained as part of the audited FPC system.

Failure to comply with all specifications will invalidate the certification and may jeopardise the fire performance.

IFC Certification Ltd

Ground Floor, Suite A, Building 2
Bear Brook Office Park
Walton Street
Aylesbury
Buckinghamshire
HP21 7GQ

United Kingdom

T +44 (0)1844 276920 www.ifccertification.com FC Certification



Page 2 of 2